INSTRUCTIONS

Carrier
A United Technologies Company
NORTH AMERICAN OPERATIONS

Instruction Sheet Number: 99TA506115 Revision:

Description: INDUCER MOTOR

Author: R. Seoane Date: November 1, 1988

Part Number: HC24AU461

When using the HC24AU461 as a service replacement for HC24AU725, check the shaft diameter of the new motor.

If the shaft starts with a diameter of 1/4” and then increases to 5/16”, the blower wheel hub will have to be drilled out to 5/16”. If the shaft is 1/4” diameter for the full length, DO NOT drill out the hub.